VKBA 3937

Teknisk bulletin - November 2011

Chevrolet Epica – Främre hjullager – kontroll av ABS-utförande

Teknisk information: VKBA 3937

ABS-utföranden som monterats på liknande hjullager på vissa Chevrolet-modeller kan fungera annorlunda. Detta kan leda till att fel lagerenhet monteras, vilket i sin tur kan göra att ABS-felkoder aktiveras i Epica-modeller från ca 2007 och liknande. Detta kan inträffa på grund av ändringar i produktion/utrustning vid den tiden.

Kontrollera innan nytt lager monteras. Lagret och ABS-konstruktionen måste kontrolleras – jämför med bilens gamla del för att säkerställa att det är rätt version. Det kan lätt bekräftas genom att se på delens baksida.

OBS: olika utformade ABS-sensorringar finns monterade på baksidan av navet

Konstruktionstyp 1
VKBA 3937
montering OK

Konstruktionstyp 2
INTE VKBA 3937

® SKF is a registered trademark of the SKF Group.

© SKF Group 2011
The contents of this publication are the copyright of the publisher and may not be reproduced (even extracts) unless written permission is granted. Every care has been taken to ensure the accuracy of the information contained in this publication but no liability can be accepted for any loss or damage whether direct, indirect or consequential arising out of the use of the information contained herein.