BR930455, BR930459 & BR930460
Front hub installation tip

Tech tip

Please note that for certain model years from 04-08, the mounting orientation (clock position) of the ABS cord can be in either of two positions. Fig. 1 shows the ABS cord sensor head mounted in the 12 O'clock position and Fig. 2 shows the ABS sensor head mounted in the 3 O'clock position, or towards the back of the vehicle. If you experience a tight fit between the wheel speed sensor cord and the caliper mounting bracket on your vehicle when the ABS cord is mounted in the 3 O'clock or towards the back of vehicle, it can be moved to the 12 O'clock position to avoid any tight fit concerns. See Fig. 3

Fig. 1
12 O'clock position

Fig. 2
3 O'clock position

Fig. 3
Possible interference with caliper bracket

SKF Vehicle Service Market North America
890 N. State St., Suite 200
Elgin, IL 60123
1-800-882-0008 • www.vsm.skf.com